

CAUTION

The upper and lower shock mount bolts **MUST BE TIGHTENED** to a torque value of 210 to 235 ft-lbs (285 to 319 N•m). If the shock mount bolts are not properly tightened, failure of the shock absorber may occur that could damage the suspension and/or its components.

IMPORTANT: This torque value supersedes all previous torques for the shock mount bolts.

2070 Industrial Place SE
Canton, OH 44707-2600 USA
Phone (330) 456-7288
Fax (330) 456-0105

 **HENDRICKSON**
Trailer Suspension Systems

A Boler Company

250 Chrysler Drive, Unit #3
Brampton, Ontario L6S 6B6 CAN
Phone (905) 789-1030
Fax (905) 789-1033

The Boler Company, Copyright © 1998
Hendrickson Trailer Suspension Systems
All Rights Reserved