


HTB® LT Rear Air Suspension for International® Truck Vehicles


LIT NO: SP-181 **DATE**: July 2016

REVISION: D





40K Capacity





| KEY | NO. PART NO. | VEN | HICLE QTY. |
|-------------|--------------|---|---------------|
| 1 | 65700-000 | Frame Hanger | 2 |
| 2 3 4 | | *Frame Hanger Flange Hex Bolt | <u>2</u> 4 |
| 3 | | *Frame Hanger Flange Locknut | 4 |
| 4 | 77906-398 | Torque Rod Assembly, Replaces 64768-398 | 4 |
| 5 | | Torque Rod Shims A | s Req. |
| | 65640-001 | 0.030" | |
| | 65640-002 | 0.060" | |
| | 65640-003 | 0.120" | |
| 6 | 66636-00X | %"-11 UNC Torque Rod Flange Bolt, | 8 |
| | | (See chart below for length and Part No.) | |
| 7 | 66637-000 | %"-11 UNC Torque Rod Flange Locknut | 8 |
| 8 | 66193-00X | Pinion Spacer (See chart below) | 8 |
| 9 | 65708-000 | Axle Top Pad Assembly, Includes Key No. 10 | 4 |
| 10 | 64080-000 | Axle Stop | 4 |
| | 91430-051 | U-bolt Service Kit, One Wheel End, Includes Key No. 11 and Kit No. 48718-501 | |
| 11 | 64102-002 | 3/4"-16 UNF x 14" U-bolt | 8 |
| | 48718-501 | U-bolt Fasteners Service Kit, One Wheel End Includes Key Nos. 12-13 | |
| 12 | 22962-001 | 3/4" Hardened Flat Washer | 16 |
| 13 | 49685-000 | 34"-16 UNF U-bolt Locknut | 16 |
| 14 | | Lower Air Spring Bracket, Front (See chart bel | |
| 15 | | Lower Air Spring Bracket, Rear (See chart belo | ow) 2 4 |
| 16 | 80087-002 | Air Spring Assembly, <i>Replaces 66643-002L,</i> 60977-002L | 4 |
| 17 | | *½"-13 UNC Flange Nut | 4 |
| 18 | 60657-008L | Shock Absorber, Replaces 60657-006 | 4 |
| | 60657-010L | ProStar | |
| | 60657-011L | Prostar Daycab | |
| 19 | 67463-002 | Shock Absorber Frame Bracket Replaces 65000-002 | 4 |
| | 50754-022 | Upper Shock Mount Fastener Kit, One Shock Includes Key Nos. 20-21 | ۲, |
| 20 | 58917-001 | 34"-10 UNC x 41/4" Hex Bolt, Replaces 50764-0 | 10 4 |

| KE | Y NO | D. PART NO. | VE DESCRIPTION | HICLE QTY. | |
|----|------|-------------------------------------|---|---------------|--|
| 21 | | 66137-000 34"-10 UNC Flange Locknut | | | |
| 22 | | | *Lower Shock Flange Hex Bolt | 4 | |
| 23 | | | *Lower Shock Flange Locknut | 4 | |
| | | 60961-721 | Torque Box Service Kit, Single Axle, | | |
| | | | Includes Key Nos. 4, 24, 27a–29a, 36-39 | | |
| 24 | | 64785-007B | Torque Box Assembly, | 2 | |
| | | | Replaces 64785-001, 64785-002B | | |
| 25 | | | **Tall Axle Bracket | 2 | |
| 26 | | | **Short Axle Bracket | 2 2 4 | |
| 27 | | | Axle Bracket Bar Pin Clamp | 4 | |
| | α | 67157-001 | Left Hand, Vehicles built after 10/07 | | |
| | b | 66174-000 | Non-Adjustable, Vehicles built prior to 10/0 | 07 | |
| 28 | | | Axle Bracket Bar Pin Clamp | 4 | |
| | а | 67157-002 | Right Hand, Vehicles built after 10/07 | | |
| | b | 66274-000 | Adjustable, Vehicles built prior to 10/07 | | |
| 29 | | | Axle Bracket Spacer (3/32") | 8 | |
| | а | 67237-001 | Vehicles built after 10/07 | | |
| | b | 65737-001 | Vehicles built prior to 10/07 | | |
| 30 | | | *Axle Bracket Hex Bolt | 8 | |
| 31 | | | *Axle Bracket Washer | 16 | |
| 32 | | | *Axle Bracket Locknut | 8 | |
| | | | Cross Member Gusset | | |
| 33 | | 65705-001 | Left Hand Top, Right Hand Bottom | 4 | |
| 34 | | 65705-002 | Left Hand Bottom, Right Hand Top | 4 | |
| 35 | | 67478-000 | Cross Member C-Channel, Replaces 64970- | 000 2 | |
| 36 | | 65144-000 | Cross Member Bar Pin Clamp | | |
| | | 60961-722 | Torque Box Fasteners Service Kit, Single Av Includes Key Nos. 29a, 37-39 | kle, | |
| 37 | | 32043-022 | %"-11 UNC x 8¾" Cross Member Hex Bolt | 16 | |
| 38 | | 22962-004 | %" Cross Member Washer | 16 | |
| 39 | | 66637-000 | %"-11 UNC Cross Member Flange Locknut | 16 | |
| | | | Replaces 47764-000 | | |
| 40 | | | *Height Control Valve and Linkage Assembly | 1 | |

NOTE:

- * Not supplied by Hendrickson, used for reference only. Hendrickson is not responsible for components supplied by the vehicle manufacturer. For assistance with maintenance and rebuild instructions on these components see vehicle manufacturer.
- ** Supplied to the axle manufacturer by Hendrickson. Hendrickson is not responsible for installation of the axle brackets installed by the axle manufacturer. For assistance with maintenance and rebuild instructions on these components, see the axle manufacturer.

HTB LT PINION ANGLE CHART

| | | Key No. 14, 15 | | Key No. 8 | | Key No. 6 | |
|-------|--------------|-----------------------------|------------|---------------|-----------|------------------------|-----------|
| | Pinion Angle | Air Spring Bracket Part No. | | Pinion Spacer | | Torque Rod Flange Bolt | |
| | | Left Hand | Right Hand | Thickness | Part No. | Length | Part No. |
| | 2° | 65638-001 | 65638-002 | None | None | 31/2" | 66636-004 |
| FRONT | 3° | | | 8 mm | 66193-001 | 4" | 66636-003 |
| FRONI | 4° | | | 16 mm | 66193-002 | | |
| | 5° | | | 24 mm | 66193-003 | 41/2" | 66636-002 |
| | 8° | 65698-001 | 65698-002 | 24 mm | 66193-003 | 41/2" | 66636-002 |
| REAR | 9° | | | 16 mm | 66193-002 | 4" | 66636-003 |
| | 10° | | | 8 mm | 66193-001 | | |
| _ | 11° | 64764-001 | 64764-002 | 24 mm | 66193-003 | 4½" | 66636-002 |
| REAR | 12° | | | 16 mm | 66193-002 | | |
| | 13° | | | 8 mm | 66193-001 | 4" | 66636-003 |

SP-181 3

This is a general parts list to provide directional information. Components may vary by model. Questions in regards to parts, contact Hendrickson Truck Parts at 1.866.755.5968 (Toll-free U.S. and Canada), 630.910.2800 (Outside U.S. and Canada) or email: truckparts@hendrickson-intl.com.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications, and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 1.866.755.5968 (toll-free) or 1.630.910.2800 for additional information.



www.hendrickson-intl.com

TRUCK COMMERCIAL VEHICLE SYSTEMS

800 South Frontage Road Woodridge, IL 60517-4904 USA 1.866.755.5968 (Toll-free U.S. and Canada) 1.630.910.2800 (Outside U.S. and Canada) Fax 1.630.910.2899

© 2005–2016 Hendrickson USA, L.L.C. All Rights Reserved. All trademarks shown are owned by Hendrickson USA, L.L.C., or one of the affiliates, in one or more countries.

Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected.