

## TIREMAAX® CP TIRE INFLATION SYSTEM

This TIREMAAX® CP controller assembly has been factory preset to:

**100 psi**

If the lamp remains on continuously for more than 10 minutes, one or more tires may be low or the system requires service.

Install the enclosure so drain hole is located on the bottom.

For complete service details, refer to Hendrickson publication L995, TIREMAAX CP Installation, Service and Troubleshooting Procedures, or call the Hendrickson technical service department at 800-455-0043 in the United States or 800-668-5360 in Canada.

Trailer Suspension Systems  
2070 Industrial Pkcs SE  
Canton, OH 44707-2641 USA  
866.RIDEAIR (743.3247)  
330.489.0045  
Fax 800.696.4416



Trailer Suspension Systems  
250 Chrysler Drive, Unit #3  
Brampton, ON Canada L6S 6B6  
905.789.1030  
Fax 905.789.1033