

# **H** PARTS LIST

## HT™ SERIES HT300YB SUSPENSIONS

LIT NO: L1271

DATE: December 2017

---




# HT300YB PARTS LIST



Picture shown may not resemble all models.

## HT300YB





# HT300YB PARTS LIST

ITEM	DESCRIPTION	PART NO.	QTY.	NOTE
<b>1</b>	<b>BEAM ASSEMBLY</b>			
	Standard, roadside, QUIK-ALIGN®	S-31377-3	1	
	Standard, curbside, QUIK-ALIGN	S-31377-4	1	
<b>2</b>	<b>BUSHING ASSEMBLY</b>	S-30862	2	
<b>3</b>	<b>TUBE SLEEVE</b>	S-7342	2	
<b>4</b>	<b>ALIGNMENT COLLAR</b>			
<b>4a</b>	Eccentric washer, QUIK-ALIGN	S-20925	2	Bolt hole is offset from center of collar
<b>4b</b>	Concentric washer, QUIK-ALIGN	S-20924	2	Pivot bolt hole is center of collar
<b>5</b>	<b>BUSHING TUBE SPACER</b>	S-11613	4	
<b>6</b>	<b>QUIK-ALIGN PIVOT BOLT KIT</b>	S-25948	2	Includes shear-type bolt, nut & washers
<b>7</b>	<b>U-BOLT KIT, RD</b>	S-3650/4	4	
<b>8</b>	<b>TRI-FUNCTIONAL® II BUSHING KIT</b>	S-26000	2	Includes bushing assembly, bushing tube spacers, bolt & nut
<b>9</b>	<b>AIR SPRING PLATE</b>			
	HT300YB.XXXX	S-23294	2	
	HT300YB-XX-XXX	A-24966	2	
<b>10</b>	<b>AIR SPRING</b>			
	HT300YB.XXXX	S-25319	2	
	HT300YB-XX-XXX	S-3830	2	
<b>11</b>	<b>AIR SPRING BOLT KIT</b>			
	HT300YB.XXXX	S-25339/2	2	
	HT300YB-XX-XXX	S-1981/2	2	
<b>12</b>	<b>UPPER SHOCK CLEVIS</b>			
	HT300YB.XXXX	S-20113	2	
	HT300YB-XX-XXX	S-2592	2	
<b>13</b>	<b>SHOCK ABSORBER</b>	S-20002	2	
<b>14</b>	<b>SHOCK BOLT KIT</b>	S-2157/2	2	
<b>15</b>	<b>LOWER SHOCK CLEVIS (Not Shown)</b>			
	Standard, roadside	S-20145-1	1	
	Standard, curbside	S-20145-2	1	
<b>16</b>	<b>SHOCK STRAP KIT (Not Shown)</b>			
	For A-20002 shock absorber	S-14587-1	1	

NOTE: US/YB can be identified by Dual Combo Stud A/S & YB "dot number" YB.XXX

NOTE: UB/YB only consists of two part numbers HT300YB-7.5-001 or HT300YB-9-001

Call your trailer dealer or Hendrickson at **330.489.0045** or **866.RIDEAIR (743.3247)** for additional information.



[www.hendrickson-intl.com](http://www.hendrickson-intl.com)

**TRAILER COMMERCIAL VEHICLE SYSTEMS**

2070 Industrial Place SE  
Canton, OH 44707-2641 USA  
866.RIDEAIR (743.3247)  
330.489.0045 • Fax 800.696.4416

**Hendrickson Canada**

250 Chrysler Drive, Unit #3  
Brampton, ON Canada L6S 6B6  
800.668.5360  
905.789.1030 • Fax 905.789.1033

**Hendrickson Mexicana**

Círculo El Marqués Sur #29  
Parque Industrial El Marqués  
Pob. El Colorado, Municipio El Marqués,  
Querétaro, México C.P. 76246  
+52 (442) 296.3600 • Fax +52 (442) 296.3601