


# AVAILABLE LITERATURE TRAILER SUSPENSION SYSTEMS

**SUBJECT:** Pivot Bushing Inspection /  
Replacement Information

**LIT NO:** L1071

**DATE:** April 2016

**REVISION:** B



To assist with pivot bushing inspection, service and replacement, Hendrickson has made the following literature available on our website:

[www.Hendrickson-intl.com/TrailerLit](http://www.Hendrickson-intl.com/TrailerLit)

<u>B31</u>	Torque Specifications
<u>B106</u>	Pivot Bushing Inspection Procedure
<u>L427</u>	Bushing Replacement Procedure
<u>L466</u>	Bushing Tool Instructions
<u>L579</u>	Alignment Procedure
<u>L589</u>	TRI-FUNCTIONAL® Bushing Replacement Tool Parts List
<u>L750</u>	Bushing Tube Spacer Inspection / Replacement Procedure
<u>L1072</u>	Pivot-Connection Fastener Information
<u>T82001</u>	TRI-FUNCTIONAL® Bushing Tool Information
<u>MSDS</u>	Extreme Pressure Lube #3
<u>MSDS</u>	S.G. Type M Rubber Assembly Oil

For any questions on suspension literature or installation drawings, contact **Hendrickson Trailer Technical Services**, in the United States and Canada at 866-RIDEAIR (743-3247) or e-mail [HTTS@Hendrickson-intl.com](mailto:HTTS@Hendrickson-intl.com).

Call Hendrickson at **866.RIDEAIR (743.3247)** for additional information.



[www.hendrickson-intl.com](http://www.hendrickson-intl.com)

#### TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE  
Canton, OH 44707-2641 USA  
866.RIDEAIR (743.3247)  
330.489.0045 • Fax 800.696.4416

#### Hendrickson Canada

250 Chrysler Drive, Unit #3  
Brampton, ON Canada L6S 6B6  
800.668.5360  
905.789.1030 • Fax 905.789.1033

#### Hendrickson Mexicana

Circuito El Marqués Sur #29  
Parque Industrial El Marqués  
Pob. El Colorado, Municipio El Marqués,  
Querétaro, México C.P. 76246  
+52 (442) 296.3600 • Fax +52 (442) 296.3601