

HXL5[®] HENDRICKSON EXTENDED-LIFE 5-YEAR SYSTEM[™] WHEEL END

- * **DO NOT remove the HXL5[®] hubcap without first contacting Hendrickson Trailer Technical Services Department in the United States and Canada at 866-RIDEAIR (743-3247).**
- **HXL5 is equipped with a PRECISION320[®] nut system on a HP spindle or a PRECISION240[®] nut system on a HN spindle.**
- **Do not add lubricant, hub is pre-filled with Chevron Delo[®] SYN-GREASE[™] SFE EP or APPROVED SEMI FLUID GREASE (See T72013).
DO NOT MIX LUBRICANTS.**
- **Quarterly rotate wheel end to ensure smooth and quiet rotation (T72002).
If not smooth and quiet rotation, contact Hendrickson.***
- **Monthly visually inspect hubcap and back of hub for evidence of lube leaks.**

**NOTE: Wheel-end repairs performed prior to contacting Hendrickson Technical Services voids the warranty.
Refer to L583 for details.**

Trailer Commercial Vehicle Systems
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045
FAX 800.696.4416



www.hendrickson-intl.com

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
905.789.1030
FAX 905.789.1033