

H TECHNICAL BULLETIN

CAP STYLE BUSHING TUBE SPACER

LIT NO: L925

DATE: June 2006

Beginning mid-July, Hendrickson Trailer Suspension Systems will begin installing the cap style bushing tube spacer as a standard component on the following suspension models. Part numbers for these models will remain unchanged.

Non-High Control Suspensions


INTRAAX® — AAEDT 30K, AAT 30K, AAEDL 30K and AAL 30K

HT™ Series — HT300 Top Mount

High Control Suspensions

INTRAAX — AAEDT 30K, AAT 30K, AAT 25K, AAT 23K, AAEDL 30K, AAL 30K, AAL 25K and AAL 23K

HT Series — HT300 Top Mount, HT250T



Cap Style Bushing Tube Spacer

In addition, the cap style bushing tube spacer will be an available option on the models noted below. If you choose to purchase the cap style bushing tube spacer as an option, a new part number will be provided for ordering purposes.

Non-High Control Suspensions

INTRAAX — AAT 25K, AAT 23K, AAL 25K and AAL 23K

HT Series — HT250T

SUMMARY TABLE

SUSPENSION MODEL	NON-HIGH CONTROL		HIGH CONTROL		
	CAP STYLE	FLAT	CAP STYLE	FLAT	
INTRAAX	AAEDT 30K	std.	N/A	std.	N/A
	AAT 30K	std.	N/A	std.	N/A
	AAT 25K	opt.	std.	std.	N/A
	AAT 23K	opt.	std.	std.	N/A
	AANT 23K	N/A	std.	N/A	std.
	AAEDL 30K	std.	N/A	std.	N/A
	AAL 30K	std.	N/A	std.	N/A
	AAL 25K	opt.	std.	std.	N/A
	AAL 23K	opt.	std.	std.	N/A
	AANLS 20K	N/A	std.	N/A	std.
HT™ Series	HT300	std.	N/A	std.	N/A
	HT250T	opt.	std.	std.	N/A
	HT230	N/A	std.	N/A	std.
	HT300U	N/A	std.	N/A	std.
	HT250US	N/A	std.	N/A	std.
	HT250U	N/A	std.	N/A	std.
	HT190U	N/A	std.	N/A	std.

IMPORTANT: Cap style bushing tube spacers are required for logging and petroleum tanker applications. Work with your Hendrickson sales associate or customer service representative to assure the proper spacer is specified.

If you have any questions regarding this change, please call Hendrickson at 1-866-RIDEAIR (743-3247).

Call Hendrickson at **866.RIDEAIR (743.3247)** for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada

250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601