

# **H** HT™ SERIES

## HT190TB & TA SPECIFICATIONS

LIT NO: L111

DATE: January 2020

REVISION: F

---





APPLICATIONS		
<b><sup>1</sup> CAPACITY</b>	20,000 lbs. suspension (9 000 kg)	
<b>TRAILER TYPES</b>	<b>UNITED STATES AND CANADA</b> Van Reefer	<b>MEXICO, CENTRAL AND SOUTH AMERICA</b> None
<b>AXLE DATA</b>	5-inch diameter round, 5/8-inch min. wall <sup>2</sup> , 15-inch or 16.5-inch drum brakes	
<b>AXLE ARRANGEMENT</b>	Single or tandem (up to 122-inch max. axle spacing)	
<b>FRAME TYPES</b>	Steel only	
<b>BASE MODEL DESCRIPTION:</b>	HT™ Series top-mount suspension, weld-on wingless frame brackets (TB) with QUIK-ALIGN® and rear mount shocks standard.	
<b>OTHER OPTIONS:</b>	Additional options include winged frame brackets (TA). Contact your Hendrickson representative to discuss these and other product options.	

## SPECIFICATIONS

SUSPENSION — HT190TA & TB (Base Models) <sup>3</sup>			
<b>RIDE HEIGHT (inches)</b>	<b>JOUNCE (inches)</b>	<b>REBOUND (inches)</b>	<b>WEIGHT <sup>4</sup> (pounds)</b>
14	3.1	4.1	269
15	3.3	4.3	280
16	3.1	4.1	298
17	3.3	4.4	302

1. Capacity refers to suspension ratings, except where noted. Ratings for brakes and wheel-end components differ depending upon options chosen.
2. Refer to literature number L980 for Hendrickson axle capacity rating recommendations. A thicker axle wall should be considered in more demanding applications.
3. Other models and options are available.
4. Weight shown does not include the axle.

*Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.*

*All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.*

**Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.**



www.hendrickson-intl.com

**TRAILER COMMERCIAL VEHICLE SYSTEMS**  
2070 Industrial Place SE  
Canton, OH 44707-2641 USA  
866.RIDEAIR (743.3247)  
330.489.0045 • Fax 800.696.4416

**Hendrickson Canada**  
250 Chrysler Drive, Unit #3  
Brampton, ON Canada L6S 6B6  
800.668.5360  
905.789.1030 • Fax 905.789.1033

**Hendrickson Mexicana**  
Circuito El Marqués Sur #29  
Parque Industrial El Marqués  
Pob. El Colorado, Municipio El Marqués,  
Querétaro, México C.P. 76246  
+52 (442) 296.3600 • Fax +52 (442) 296.3601