

Peterbilt® 384 / 386 AERO CLAD®

AERO CLAD® bumpers for Peterbilt® 384 / 386 tractors offer a bright mirror finish in a lightweight package that is more durable than traditional chromed bumpers with less maintenance. Unlike traditional chrome or painted bumpers, AERO CLAD bumpers resist corrosion, cracking, pitting, peeling and fading. Backed by a 5-year limited warranty*, AERO CLAD bumpers bring the quality and reliability that customers have come to expect from Hendrickson.

* Contact your local Hendrickson representative for complete warranty terms, conditions and limitations.



0889NLSSC



To learn more about AERO CLAD, call 815.727.4031 or visit www.hendrickson-intl.com/bumper



AERO CLAD® Features and Benefits

- Lightweight to help enhance fuel efficiency
- · Easy installation to factory mounts
- · Durable, bright mirrored finish
- Finish up to 10 times thicker than typical chrome finish
- Increased weight savings up to 150 lbs. compared to OEM steel bumper
- Resists corrosion, cracking, pitting, peeling and fading
- · Minor abrasions can be buffed
- Quality, American-made product
- Full 5-year limited warranty*

NOTE: For use on all models with set forward axle and front drop casting or center tow.

Peterbilt® 354 / 386 Bumper Specifications

PART NO.	MATERIAL / FINISH	GAUGE / THICKNESS	STYLE	LIGHT	CENTER STEP	VENT	TOW	RADAR	EXCLUSIVE THROUGH OEM	YEAR	MOUNT / BRACKET
0889NLSSC	AERO CLAD®	0.125	13.6"	N	Y	N	Υ	N	Υ	'06 - '15	Υ
0889SSC	AERO CLAD	0.125	14" Closed End	Rectangular	Y	N	Υ	N	Υ	'06 - '1 5	Υ

MA28U2210-28 (0889SSC) — With Light Cutouts — Direct replacement of OEM Part N71-6061-007 MA28U0210-28 (0889NLSSC) — Without Light Cutouts — Direct replacement of OEM Part N71-6061-005 Two-piece air dam available from Peterbilt — Left side p/n N33-6030 and Right side p/n N33-6030R



Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration.

Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 815.727.4031 for additional information.



HENDRICKSON BUMPER 501 Caton Farm Road

Lockport, IL 60441 USA 815.727.4031 hbatcustservice@hendrickson-intl.com

www.hendrickson-intl.com

^{*} Contact your local Hendrickson representative for complete warranty terms, conditions and limitations.